



Category C - Phase II of GWF Tracy

- j) A single-line-to-ground fault at one of the line breakers at the Tesla 230 kV bus Section E, with a breaker failure condition.**


Plot 1	Project Terminal Voltages and Angles
Plot 2	Project Power and Speed
Plot 3	Selected Bus Voltages Adjacent to Fault
Plot 4	Selected Bus Frequencies Adjacent to Fault




GWF Tracy Peaking Plant Project (Phase 2 - 258 MW)
 2004 Summer Peak Base Case, Stability Study
 Phase 2 w/ GWF ET 1 & 2 and ST each @ 86.0 MW
 SLG fault at Tesla 230 kV Bus Section E
 with a tie breaker failure condition.



GWF Tracy Peaking Plant Project (Phase 2 - 258 MW)
2004 Summer Peak Base Case, Stability Study
Phase 2 w/ GWF ET 1 & 2 and ST each @ 86.0 MW
SLG fault at Tesla 230 kV Bus Section E
with a tie breaker failure condition.



GWF Tracy Peaking Plant Project (Phase 2 - 258 MW)
 2004 Summer Peak Base Case, Stability Study
 Phase 2 w/ GWF CT 1 & 2 and ST each @ 86,0 MW
 SLG fault at Tesla 230 kV Bus Section E
 with a tie breaker failure condition.



GWF Tracy Peaking Plant Project (Phase 2 - 258 MW)
 2004 Summer Peak Base Case, Stability Study
 Phase 2 w/ GWF CT 1 & 2 and ST each @ 86,0 MW
 SLG fault at Tesla 230 kV Bus Section E
 with a tie breaker failure condition.